G3632/G1479 INSTRUCTIONS



WHEN THE PROBE CONTACTS WORK PIECE OR OBJECT TO BE INDICATED, IT MOVES UP AND ROTATES THE HAND. TO ZERO HAND, LOOSEN DIAL FACE RING LOCKNUT. THEN TURN DIAL FACE RING UNTIL ZERO LINES UP WITH HAND. THEN YOU MAY TIGHTEN DIAL FACE RING LOCKNUT. THE POINTERS CAN BE MOVED INDEPENDENTLY TO SHOW ACCEPTABLE LIMITS OF TOLERANCE.

© Grizzly Industrial, Inc.1995